



Norsonic AS
Gunnerstråtan 2
N-3409 Tranby
Norway
Tel: +47 3285 8900
info@norsonic.com
www.norsonic.com

Supplier's Declaration of Conformity 47 CFR § 2.1077 Compliance Information

Unique identifier: Precision Sound Analyser Nor145, Nor1209 / Nor1209A preamplifier

Responsible Party - U.S. Contact Information:

Scantek, Inc.
6430 #C, Dobbin Rd
Columbia, MD 21045

Phone: +1 410-290-7726 | info@scantekinc.com | www.scantekinc.com

FCC Compliance Statement: Nor145 and Nor145 with uBlox Toby L200 cellular module and Ella W131 WiFi module.

This device complies with Part 15 class B of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Contains FCC ID: XPYTOBYL200 and FCC ID : PV7-WIBEAR11N-SF1

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna
- Increase the separation between the equipment and receiver
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected
- Consult the dealer or an experienced radio/TV technician for help